

25X1A

CLASSIFICATION <u>SECRET</u>		25X1	
COUNTRY <u>East Germany</u>	REPORT NO. <u>619779</u>		
TOPIC <u>Oranienburg Airfield</u>		25X1A	
EVALUATION <u>see below</u>	PLACE OBTAINED <u>25X1A</u>		
DATE OF CONTENT <u>12 February to 8 March 1954</u>			
DATE OBTAINED <u>25X1A</u>	DATE PREPARED <u>2 April 1954</u>		
REFERENCES <u>1</u>	25X1A		
PAGES <u>1</u>	ENCLOSURES (NO. & TYPE)		
REMARKS			

SOURCE

25X1X

25X1X

1. On 12 February 1954, 25X1X

large patches on the concrete runway at Oranienburg airfield had been damaged by frost. 25X1X the entire fuel dump was to be provided with lighting facilities on poles and that the runway was to be lighted by ground lamps. The boundary lights could not be put in operation as the transformer for them had not yet arrived.

2. At the beginning of March, source determined that damages had occurred to the runway and taxiways, particularly in the northern section of the field. Some concrete slabs had risen up to 8 cm. The taxiway between the hangar and the runway was most seriously damaged. The middle and southern sections of the runway had frost bulges of 1 to 4 cm.
3. At the beginning of March, electricians of the Leipzig Bauunion were engaged in laying light wires and in installing an transformer at the field. This work had not been completed by 10 March. One of the electricians was arrested by the Soviets on 9 March. The fuel dump was not yet in operation by 5 March.

4. The field was not occupied by a Soviet Air Force unit until 8 March. Two Soviet soldiers wearing black-bordered blue epaulets and armed with machine guns were observed at the field on 8 March.

25X1A 25X1A Comment. The damages to the runway and taxiway at Oranienburg airfield caused by the frost have repeatedly been reported. These damages delayed the turning over of the airfield to the Soviets and the occupation of the field by an air unit.

CLASSIFICATION

SECRET

25X1